





Section G.1 Gauges

G.1.1	For All Versions	G.1-2
G.1.2	For Those Versions Equipped with a Tappet Cam Shedding Motion.....	G.1-2
G.1.3	For Those Versions Equipped with a Crank Shedding Motion.....	G.1-3

G. GAUGES, TOOLS, AND MEASURING INSTRUMENTS



G.1 Gauges

G.1.1 For All Versions

No.	Gauge No.	Name	Dimensions	Shape	Q'ty/ machine	Remarks
1	77134-00004	Thickness gauge	0.03 0.09 0.2 0.5 0.04 0.1 0.25 0.6 0.05 0.11 0.3 0.7 0.06 0.13 0.35 0.8 0.07 0.14 0.4 0.9 0.08 0.15 0.45 1.0		1	
2	J8211-02011-**	Electromagnetic-pin gauge		 (White)	1	For blower-less measurement
3	J8201-06010-**	Belt tension gauge			1	For setting the belt tension in the take-up motion and the main drive mechanism.
4	76201-00003	Belt tension gauge			1	CC gear for blower-less measurement







G.1.2 For Those Versions Equipped with a Tappet Cam Shedding Motion

REFERENCE: The gauges listed below are provided only for those versions equipped with a tappet cam shedding motion.

No.	Gauge No.	Name	Dimensions	Shape	Q'ty/ machine	Remarks
1	J8207-01010-**	Cam setting pin	ø6 × 160 L		1	For plain-weave tappets.
2	J8207-01020-**	Tappet gauge			1	For twill-, satin-, and corduroy-weave tappets.

G.1.3 For Those Versions Equipped with a Crank Shedding Motion

REFERENCE: The gauges listed below are provided only for those versions equipped with a crank shedding motion.

No.	Gauge No.	Name	Dimensions	Shape	Q'ty/ machine	Remarks
1	W8205-01010-00	Shedding adjustment gauge	M6 × 36 L Punch mark : H		2	Standard stroke
2	W8205-01020-00	Shedding adjustment gauge	M6 × 38.5 L Punch mark : M		2	Standard stroke
3	W8205-01030-00	Shedding adjustment gauge	M6 × 41 L Punch mark : L		2	Standard stroke
4	W8205-01040-00	Shedding adjustment gauge	M6 × 42 L Punch mark : HS		2	Short stroke
5	W8205-01050-00	Shedding adjustment gauge	M6 × 44.5 L Punch mark : MS		2	Short stroke
6	W8205-01060-00	Shedding adjustment gauge	M6 × 47 L Punch mark : LS		2	Short stroke

